

Case Study Data Form

Identifier/name **PW**

Place (town if possible) **Bicester**

Type of property (domestic/commercial) (Detached/semi/terrace/flat) **Detached**

Number of times flooded **3 times since 2007**

Type of flooding or flood risk **Pluvial**

Risk band **N/A**

Resistant measures installed **None**

Resilient measures installed - **System was installed which included NRV's to the WC and sink waste, sump with automatic pump, lift off door barriers to doors.**

Tested by flooding? **Yes but water came in through walls as the flood was prolonged and client did not take our advice to do the walls as well.**

Cost of installation **£12k**

Who paid **The property owner**

Was it installed during reinstatement **No**

Are they covered **Yes**

Did the installation give cheaper cover **Yes**

Any important additional information **The property flooded again in 2008 and was more prolonged than the 2007 flood and the client paid for us to upgrade the system to include the walls of the property at an additional cost of £12k.**

After

